Publication Part No. 6F6595
15 MAR 04
Supercedes 927 0532
10 NOV 03

INSTALLATION INSTRUCTIONS

for the

PIERCER IMPROVEMENT KIT

for the

***Kodak* AUTOMIXER II**
Service Code: 3112

***Kodak* AUTOMIXER II Plus**
Service Code: 3439

Important

Qualified service personnel must install this equipment.

HEALTH IMAGING

Confidential, Restricted Information
©Eastman Kodak Company 2003

PLEASE NOTE: The information contained herein is based on the experience and knowledge relating to the subject matter gained by Eastman Kodak Company prior to publication.

No patent license is granted by this information.

Eastman Kodak Company reserves the right to change this information with out notice, and makes no warranty, express or implied, with respect to this information. Kodak shall not be liable for any loss or damage, including consequential or special damages, resulting from any use of this information, even if loss or damage is caused by Kodak's negligence or other fault

Installation

Purpose

If chemistry drains slowly from the bottles, because the PIERCER in *Kodak* AUTOMIXER II or AUTOMIXER II Plus does not pierce the cap and seal completely, you will need to install the following parts:

MODEL of Automixer	**Part Numbers Required**	**Parts Needed for each AUTOMIXER**
AUTOMIXER II	9171279	2 (one for each PIERCER for BOTTLE "A")
AUTOMIXER II Plus	9270531	2 (one for each PIERCER for BOTTLE "A")
Installation Instructions	6F6595	1

These parts are available from Service Parts Management.

Installing the new PIERCER Parts to an AUTOMIXER II Plus

Important

These parts improve piercing of the cap and seal of the chemistry bottles, do NOT remove the existing PIERCERS.

Warning

Dangerous Voltage

1. De-energize and disconnect the main power from the AUTOMIXER.



2. Open the TOP COVERS and remove any empty BOTTLES, that may be inserted into the MIXER.



2. Install INSERT onto the PIERCER used for BOTTLE "A" for DEVELOPER and FIXER, making sure to align the opening over the moveable blade. Make sure tabs on INSERT lock underneath the PIERCER

2. Close the TOP COVERS.

3. Energize the AUTOMIXER and check for correct operation.

Installing the new PIERCER Parts to an AUTOMIXER II

Important

These parts improve piercing of the cap and seal of the chemistry bottles, do NOT remove the existing PIERCERS.

Warning

Dangerous Voltage

1. De-energize and disconnect the main power from the AUTOMIXER.
2. Open the TOP COVERS and remove any empty BOTTLES, that may be inserted into the MIXER.

Caution

New blades have sharp points, use extreme caution when handling and installing!

3. Install the 2 interlocking new blades over the existing PIERCERS used for BOTTLE "A" for DEVELOPER and FIXER.



4. Close the TOP COVERS.

5. Energize the AUTOMIXER and check for correct operation.

Publication Date	Publication No.	ECO No.	Changed Pages	File Name	Notes
15 OCT 03	927 0532	-------	--------	AM2 Piercer.doc	New Publication
15 MAR 04	6F6595	-------	All	AM2 Piercer.doc	Publication part number changed only, content remains the same.

Kodak, Min-R, Industrex, and X-Omat **are trademarks.**

Printed in the U.S.A.
EASTMAN KODAK COMPANY
Rochester NY 14650

HEALTH IMAGING